



QUALITROL 050

Pressure or vacuum indicators

Application

For pressure or vacuum indication on transformers and other related apparatus.

Features

- Clear visual indication of internal pressure condition

Options

- Pressure/vacuum range
- Unit of measure and dial style
- Liquid filled for high vibration